



<b>PROJECT:</b>	<b>PLOUGH MODIFICATION</b>	
		
<b>OPERATOR:</b> ROCK WATER (SINGAPORE)	<b>PROJECT VALUE:</b> NOT KNOWN	
<b>PROJECT DESCRIPTION:</b>  Existing “gunanusa” plough had to be modified for pipe burial project. The diameter of pipeline to be buried was 20 inches.  Date :            1992		
<b>CLIENT:</b>  ROCK WATER (SINGAPORE)	<b>CONTACT PERSON:</b>  Mr. Eng Bee	
<b>ZEE’S SCOPE OF WORK:</b>  To carry out the structural integrity of the plough.  A detailed Finite Element structural analysis was carried out.          <b>ZEE’S VALUE OF WORK:</b> 50,000.00 US\$		